NETWORK CHECKOUT

As of 15 July we had contacted or been contacted by the sites
listed below. The matrix indicates the elements of Network software
we have verified at each site.

	NCP-1	NCP-107	ICP 80	User Telnet	Server Telnet	Telnet-like Protocol	Log-on Procedure	Accessed Services
SDC	x							
UCLA-91		x		x	x			
UCLA-S7	x	x	x	x	x		x	x
SRI-10		x				x	x	
UCSB	x	x	x				x	x
MIT-10		x		x				
MIT-645		partial						
LL-67	x		x		x			
BBN-10		x				x	x	x
UTAH	x	x	x			x		

Notes

   SRI-10:   The Telnet-like protocol differs from Telnet in
             that lines are terminated by X'OD' rather than
             X'ODOA'. John Melvin will have it fixed by
             the time you read this.

```
LL-67:      Joel Winett telles me NCP, ICP, EBCDIC, Telnet and
            access to a virtual 360 are working.  Due to hard-
            ware difficulties we have not verified this.
BBN-10:     Same difference as SRI with respect to Telnet.
            Under certain conditions, the ICP generates a
            zero byte size.  Ray Tomlinson tells me these
            idiosyncracies will be taken care of in about
            a week.  Three sites have commented that TENEX
            assigns the same local socket to multiple connec-
            tions, when acting as a server.  Ray says that
            this is the design -- not an error.  BBN TENEX
            is currently being used productively via the
            Net, for some non-Network related problems.
UTAH:       Our tests with UTAH were pre-TENEX.  TENEX is
            currently being installed at UTAH.
MIT-645:    Our understanding is that most software is
            working; we have not verified this.
```

```
          [ This RFC was put into machine readable form for entry ]
           [ into the online RFC archives by Paul Williams 6/97 ]
```